# Warrenty Claim 2006 for Jabsco Hoddesdon

| Nr. | Part.No. | Qty. | Serial Nr./Fab.d. | Reason fo failure |
|---|---|---|---|---|
| 1 | 31750-0000 | 1 | 03C42512 | no function of sensor |
| 2 | | 1 | 03H19447 | no function of sensor |
| 3 | | 1 | 04D47679 | no function of sensor |
| 4 | 31755-0000 | 2 | 04E32028 | magnet got loosen in housing |
| 5 | | 1 | 04F23862 | failed electronic |
| 6 | | 1 | 05B25612 | failed electronic |
| 7 | | 1 | 05F41902 | failed electronic |
| 8 | R4515743A | 2 | 05E26772 | no function of sensor |
| 9 | R4525743A | 1 | 05G61640 | no function of sensor |
| 10 | | 1 | 04C14550 | no function of sensor |
| 11 | | 1 | 05J15298 | no function of sensor |
| 12 | R4325143 | 1 | 06F30000 | high current up to 12Amp. / At cut of pressure/ low performance/ out pu 11ltr only |
| 13 | R4325343 | 1 | 05I44548 | lose motor power / out put 10,5ltr only / pump head in good condition |
| 14 | 31820-0492 | 1 | 06B18401 | new from stock, dead motor, not heating, unused |
| 15 | 31600-0094 | 1 | 05B14357 | leckage at pressure switch |
| 16 | | 1 | 05J14746 | cam bearing got loosen on motor shaft |
| 17 | R3526144 | 1 | 05093107 | noisy motor / lose performance |
| 18 | | 1 | 05093107 | noisy motor / lose performance |
| 19 | | 1 | 05093107 | noisy motor / lose performance |
| 20 | R3426148 | 1 | 05243871 | Noisy Motor / no cut off |
| 21 | | 2 | 05264061 | Noisy Motor / no cut off |
| 22 | | 2 | 05213590 | Noisy Motor / no cut off |
| 23 | 31295-0092 | 1 | 05223622 | noisy motor / lose performance |
| 24 | | 1 | 05484878 | Noisy Motor / no cut off |
| 25 | | 1 | 06110369 | Noisy Motor / no cut off |
| 26 | D3732H1312AR | 1 | 06??? | no function / dead motor / looks unused |
| 27 | R4125314 | 1 | 05H28039 | loosen bearing in motor |
| 28 | 31700-0394 | 1 | 05K25916 | loosen magnets |
| 29 | RLF122202A | 1 | 05113193 | hair crack in housing |
| 30 | | 1 | 05113193 | leackage at o-ring / sealing pumphousing-motor |
| 31 | RLF122002C | 1 | 06140504 | no self priming / unused |
| 32 | G575205A | 1 | 05213646 | hair crack on top of pumpcover |
| 33 | 29097-0000 | 2 | | damaged cover |
| 34 | | 3 | | bad painting from supplier |
| 35 | 37202-2012 | 4 | 06/08 | leckage at diaphram |
| 36 | 37174-0000 | 1 | | Diaphram does not seal |
| 37 | 29040-2000 | 1 | 05K0 | hair crack at cylinder |
| 38 | 29042-0000 | 3 | from toilet | for service repairing |
| 39 | SP2601-01 | 2 | from toilet | for service repairing |
| 40 | 60030-0000 | 1 | from searchlight | switch loosen plugs / no contact to searchlight |
| 41 | 29200-0120 | 1 | 06E | lose motor power |
| | | 1 | 05F | lose motor power |
| | | 1 | 05E | lose motor power |
| 42 | 30480-0000 | 1 | | broken base |
| 43 | 30500-0024 | 1 | | badly boxed from supplier / damaged |