VOLVO

INSPECTION REPORT E0604336 (Report type A)

Date 2006-05-17
Page 1(1)

Supplier	Our Reference (Issuer)	SQA Reference
ITT INDUSTRIES JABSCO **BINGLEY ROAD** **HODDESTON HERTFORDSHI** **GREAT BRITAIN**	**Dirk Blancquaert** Department/Location **VTPG / VPG** Telephone **+32 9 255 6350** Telefax **+32 9 259 0992** E-mail **dirk.blancquaert@volvo.com**	**Peter Jeraeus** Department/Location **8661 /** Telephone **+46 512 32865** Telefax **+46 512 10370** E-mail **peter.jeraeus@volvo.com**
Supplier No. **5411** Supplier Reference **STUART MOORE**		

Part No. **3817587** Description **IMPELLER KIT**

Shipping Date **2006-02-16**
Batch No. (ID) **180533**

Shipped Qty	**105**	Inspected parts	**5**	Returned Parts	
Received Qty	**105**	Non Conforming Qty		Adjusted Parts	
		- of inspected	**5**	Scrapped Parts	
		- in the batch	**105**		

Deviation code: Wrong part number
Disposition code: Other, see notes.

Description of Deviation
WRONG PARTS DELIVERED (NOT IN ACC. WITH EDI/INV./DEL.NOTE)
105x 3817587 advised but instead we
received 105x 3588476 / parts kept

Due to non compliance with Volvo Specification, the above shipment can not be accepted.
Referring to report number E0604336. Please use 8D report for reply within 14 days.
Future shipments will not be accepted if above deviation remains.

AB Volvo Penta